

FITNESS CERTIFICATE

TO BE FILLED BY THE INSPECTING OFFICER

(Assistant Engineer / Assistant executive Engineer)

- 1 Name of school : Girideepam Bethany Central School
- 2 Name of Officer : Reshmy S Kumar
- 3 Location : Kottayam ,Kottayam East
- 4 Period for which the certificate is issued : 2023-24
- 5 Type of Buiding : Details over leaf
- 6 Nature of Defect if any :
- a) Foundation and basement : Not Noticed
- b) Superstructure : Not Noticed
- c) Doors and windows : Not Noticed
- d) Wood work wrought and put up : Not Noticed
- e) Flooring : Not Noticed
- f) Miscellaneous : Not Noticed
- 7 Any major defects noticed which will render the building unsafe in any manner : Not Noticed
- 8 Whether maintenance work have been done properly : Yes
- 9 Whether the structure is sound or not for Conduiting classes : Yes. Safe for conducting classes under normal weather conditions, except the building right side of the basket ball court.

Note: 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure of flood etc.

2. Any additional observation deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on...29.05.2023 ...and found to be fit/Unfit to conduct casses for the period2023-24 ...for the reasons stated above.


Place: Vadavathoor

Date: 29.05.2023

Signature: 

Designation: Assistant Engineer
PEN: 687881
LID & EW Section
Vijayapuram Grama Panchayath





Fr. Joseph K.J O.I.C
Principal
Girideepam Bethany Central School
Bethany Hills, Vadavathoor P.O.
Kottayam, Kerala - 686 010

Details of buildings (Dimensions)

Girideepam Bethany Central School

Below basement floor	=	600.97 sqm	
Basement floor	=	522.64	(excluded the area of building right side of basket ball court)
ground floor	=	1018.075	(excluded the area of building right side of basket ball court)
First floor	=	1481.135	(excluded the area of building right side of basket ball court)
Second floor	=	1498.34	(excluded the area of building right side of basket ball court)
Third floor	=	1958.69	
Terrace floor	=	45.74 sqm	



Reshmy
RESHMY. S. KUMAR
Assistant Engineer
PEN: 687881
LID & EW Section
Vijayapuram Grama Panchayath
Vadavathoor P.O.,
Kottayam Dist, P.N: 686 010



Fr. Joseph K.J.O.I.C
Fr. Joseph K.J.O.I.C
Principal
Girideepam Bethany Central School
Bethany Hills, Vadavathoor P.O.
Kottayam, Kerala - 686 010